

B. Recall Subject: 03V-111 Fuel Pump Failure
Report Quarter: 4th Quarter

1. NHTSA Assigned Campaign Number: 03V-111
Company Assigned Number: Bulletin V-02-06
2. Date Notification Began: April 11, 2003
Date Notification was Completed: April 18, 2003
3. Number of Vehicles Involved: 1,786
4. Number of Vehicles Inspected and Repaired: 1,073
Number Inspected and Not Needing Repair: 0
5. Number of Vehicles Determined Unreachable for Inspection: 0

C. Recall Subject: 03V-138 Brake Fluid Leak at Rear Brake Light Switch Threads
Report Quarter: 4th Quarter

1. NHTSA Assigned Campaign Number: 03V-138
Company Assigned Number: Bulletin V-03-01(A)
2. Date Notification Began: April 25, 2003
Date Notification was Completed: April 30, 2003
3. Number of Vehicles Involved: 435
4. Number of Vehicles Inspected and Repaired: 160
Number Inspected and Not Needing Repair: 0
5. Number of Vehicles Determined Unreachable for Inspection: 0

D. Recall Subject: 03V-228 Vegas Fuel Tank Vent Obstruction (California)
Report Quarter: 3rd Quarter

1. NHTSA Assigned Campaign Number: 03V-228
Company Assigned Number: Bulletin V-03-03(A)
2. Date Notification Began: July 25, 2003
Date Notification was Completed: August 1, 2003
3. Number of Vehicles Involved: 122 CA models
4. Number of Vehicles Inspected and Repaired: 50
Number Inspected and Not Needing Repair: 0